


IN THE UNITED STATES PATENT  
AND TRADEMARK OFFICE

Patentee:	Shin Seung Park	)	I hereby certify that this paper (along with any paper referred to as being attached or enclosed) is being transmitted via EFS- Web to the U.S. Patent and Trademark Office on <b>December 3, 2007</b> .
Patent No.:	7,018,935 B2	)	
Issued:	March 28, 2006	)	
Serial No.:	10/735,228	)	
Filed:	December 12, 2003	)	
Title:	METHOD OF FORMING METAL LINE OF SEMICONDUCTOR DEVICE	)	
Group Art Unit:	1765	)	Sandip H. Patel (Reg. No. 43,848) Attorney for Patentee and Assignee
Examiner:	Lan Vinh	)	
Attorney Docket No.:	29936/39847	)	


Sandip H. Patel (Reg. No. 43,848)  
Attorney for Patentee and AssigneeREQUEST FOR CERTIFICATE OF CORRECTION  
PURSUANT TO 37 C.F.R. § 1.323

Commissioner for Patents  
P.O. Box 1450  
Alexandria, Virginia 22313-1450

**Attn: Certificate of Correction Branch**

Dear Sir:

The patentee and the assignee, through their undersigned attorney, respectfully request issuance of a certificate of correction correcting the above-identified U.S. patent as noted in the attached Certificate of Correction (Form PTO-1050).

The text at column 4, line 63 (claim 1), of the patent contains a printing error attributable to the applicant. Specifically, at column 4, line 63, the recitation "covered" should be --covering--. Support for this correction can be found in paragraph [0022] (p. 4) of the filed application, which states that a "photoresist pattern 26 is formed to cover a metal line area including the metal line plug 24L..." See also, col. 3, lines 20-22, of the issued patent.

The text at column 5, line 9 (claim 1), of the patent contains a printing error attributable to the applicant. Specifically, at column 5, line 9, the recitation "isolated each" should be --isolated from each--. Support for this correction can be found in paragraph [0025] (p. 5) of the filed application, which states that "the over-etching process to the metal fuse is carried out to eliminate the metal layer 25, which remains on the periphery of the metal fuse

**U.S. Patent No. 7,018,935 B2  
Request for Certificate of Correction  
Page 2 of 2**

pattern 25F, so that the metal fuse 245 and a metal line 250 electrically isolated from the metal fuse are formed." See also, col. 3, lines 56-60, of the issued patent.

The attached Certificate of Correction corrects the foregoing errors.

In view of the foregoing, the patent has issued with printing errors attributable to the applicant. Please charge deposit account no. 13-2855, in the amount of \$100.00 to cover the processing fee set forth at 37 CFR 1.20(a).


Should the Patent Office wish to discuss the foregoing, or any matter of form or procedure in an effort to advance issuance of a certificate of correction, the Patent Office is urged to contact the undersigned attorney.

Respectfully submitted,

MARSHALL, GERSTEIN & BORUN LLP

December 3, 2007

By:

  
\_\_\_\_\_  
Sandip H. Patel (Reg. No. 43,848)  
Attorneys for Patentee  
6300 Sears Tower  
233 South Wacker Drive  
Chicago, Illinois 60606-6357  
(312) 474-6300 TELEPHONE

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,018,935 B2

APPLICATION NO. : 10/735,228

ISSUE DATE : March 28, 2006

INVENTOR(S) : Shin Seung Park

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims:

**Col. 4, line 63:** Please delete "covered" and insert --covering-- therefor.

**Col. 5, line 9:** Please delete "isolated each" and insert  
--isolated from each-- therefor.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Sandip H. Patel

MARSHALL, GERSTEIN & BORUN LLP

233 S. Wacker Drive, Suite 6300

Sears Tower

Chicago, Illinois 60606-6357

Patent No. 7,018,935 B2